

# SUPER SPEC® INTERIOR LATEX FLAT FINISH 275

# **Features**

- · Excellent hiding
- Has easy application and can be touched up
- · Spatter resistant
- Decorative and uniform flat finish
- Quick dry
- Low odor
- Soap and water clean up

#### **General Description**

A acrylic blended latex flat finish designed for application to a wide variety of interior surfaces.

## **Recommended For**

For commercial and residential applications. For new or previously painted interior wallboard, masonry, and primed or previously painted plaster, wood or metal

# Limitations

Do not apply when air and surface temperatures are below 50° F (10° C)

#### **Product Information**

#### Colors — Standard:

White (01)

A selection of off-whites is also available in limited areas. (White and off-whites may be tinted with up to 2.0 fl. oz. of Benjamin Moore® Color Preview® colorants per gallon.)

#### - Tint Bases:

Benjamin Moore® Color Preview® Bases 1B, 2B, 3B, & 4B

#### — Special Colors:

Contact your Benjamin Moore representative

#### Certification:

#### VOC compliant in all regulated areas

Class A (0-25) over non-combustible surfaces when tested in accordance with ASTM E-84

Qualifies for LEED®
Credit
(INTERIOR FLAT)

Technical Data◊		Pastel Base
Vehicle Type		Acrylic Blended Latex
Pigment Type		Titanium Dioxide
Volume Solids		32%
Coverage per Gallon at Recommended Film Thickness		400 – 450 Sq. Ft.
Recommended Film Thickness	– Wet – Dry	3.8 mils 1.2 mils

Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.

Dry Time @ 77° F	<ul><li>To Touch</li></ul>	1 Hour
(25° C) @ 50% RH	- To Recoat	2 - 3 Hours

Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times.

Dries By		Coalescence
Viscosity		93 ± 3 KU
Flash Point		N/A
Gloss / Sheen		Flat
Surface Temperature at Application	– Min.	50° F
	– Max	90° F
Thin With		Clean Water
Clean Up Thinner		Clean Water
Weight Per Gallon		11.2 lbs
Storage Temperature	– Min.	40° F
	– Max	90° F

#### **Volatile Organic Compounds (VOC)**

46 Grams/Liter .38 Lbs./Gallon

#### **Technical Assistance**

Available through your local authorized independent Benjamin Moore® retailer. For the location of the retailer nearest you, call 1-800-826-2623, see www.benjaminmoore.com, or consult your local Yellow Pages.

♦Reported values are for Pastel Base. Contact Benjamin Moore for values of other bases or color.

#### **Surface Preparation**

Surfaces to be painted must be clean, dry, and free of dirt, dust, grease, oil, soap, wax, scaling paint, water soluble materials, and mildew. Remove any peeling or scaling paint and sand these areas to feather edges smooth with adjacent surfaces. Glossy areas should be dulled. Drywall surfaces must be free of sanding dust.

New plaster or masonry surfaces must be allowed to cure  $(30-60 \, \text{days})$  before applying base coat. Cured plaster should be hard, have a slight sheen and maximum pH of 10; soft, porous or powdery plaster indicates improper cure. Never sand a plaster surface; knife off any protrusions and prime plaster before and after applying patching compound. Poured or pre-cast concrete with a very smooth surface should be etched or abraded to promote adhesion, after removing all form release agents and curing compounds. Remove any powder or loose particles before priming.

**Difficult Substrates:** Benjamin Moore & Co. offers a number of specialty primers for use over difficult substrates such as bleeding woods, grease, crayon markings, hard glossy surfaces, galvanized metal, or other substrates where paint adhesion or stain suppression is a particular problem. Your Benjamin® retailer can recommend the right problem-solving primer for your special needs

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Carefully clean up with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

## **Primer/Finish Systems**

New surfaces should be fully primed, and previously painted surfaces may be primed or spot primed as necessary. For best hiding results, tint the primer to the approximate shade of the finish coat, especially when a significant color change is desired. **Special Note**: Certain custom colors require a Deep Color Base Primer tinted to a special prescription formula to achieve the desired color. Consult your retailer.

#### Wood, and engineered wood products:

**Primer:** Super Spec® Latex Enamel Undercoater & Primer Sealer (253) or Super Spec® Alkyd Enamel Undercoater & Primer Sealer (C245)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

Drywall:

**Primer:** Super Spec® Latex Enamel Undercoater & Primer Sealer (253)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

Plaster:

Primer: Fresh Start® All-Purpose 100% Acrylic Primer (N023) or

Fresh Start®100% Acrylic Superior Primer (046)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

**Rough or Pitted Masonry:** 

Primer: Super Spec® Latex Block Filler (160) or Super Spec®

Masonry Interior/Exterior Hi-Build Block Filler (206)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

**Smooth Poured or Precast Concrete:** 

**Primer:** Super Spec® Masonry Interior/Exterior 100% Acrylic Masonry Sealer (N/066), Fresh Start® All-Purpose 100% Acrylic Primer (N023) or Fresh Start®100% Acrylic Superior Primer (046) **Finish:** 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

Ferrous Metal (Steel and Iron):

**Primer:** Super Spec HP® Acrylic Metal Primer (P04) or Super Spec HP® Alkyl Metal Primer (P06)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

Non-Ferrous Metal (Galvanized & Aluminum): All new metal surfaces must be thoroughly cleaned with Super Spec HP® Oil & Grease Emulsifier (P83) to remove contaminants. New shiny nonferrous metal surfaces that will be subject to abrasion should be dulled with very fine sandpaper or a synthetic steel wool pad to promote adhesion

**Primer:** Super Spec HP<sup>®</sup> Acrylic Metal Primer (P04)

Finish: 1 or 2 coats Super Spec® Interior Latex Flat Finish (275)

**Repaint, All Substrates:** Prime bare areas with the primer recommended for the substrate above.

#### **Application**

Stir thoroughly before use. Apply one or two coats. For best results, use a Benjamin Moore® Professional custom-blended nylon/polyester brush, Benjamin Moore® Professional roller, or a similar product. This product can also be sprayed.

**Spray, Airless:** Fluid Pressure —1,500 to 2,500 PSI;

Tip - .013-.017 Orifice

#### Thinning/Clean Up

Thinning is unnecessary, but if required to obtain desired application properties, a small amount of clean water may be added. Never add other paints or solvents.

**Clean up:** Clean brushes, rollers and other painting tools in warm soapy water after use. Spray equipment should be given a final rinse with mineral spirits to prevent rusting.

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry empty containers may be recycled in a can recycling program. Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.

# **Environmental Health & Safety Information**

**Use only with adequate ventilation.** Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Wear an appropriate, properly fitted respirator (NIOSH approved) during application, sanding, and clean-up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.

**WARNING:** This product contains a chemical known to the state of California to cause cancer and birth defects, or other reproductive harm.

**FIRST AID**: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

**IN CASE OF SPILL** – Absorb with inert material and dispose of as specified under "Clean Up".

# KEEP OUT OF REACH OF CHILDREN PROTECT FROM FREEZING

Refer to Safety Data Sheet for additional health and safety information.